

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

K98
WNW
1/8-1/4
0.188 mi.
992 ft.

ALMAX GARAGE
2712 STILLWELL AVE
BROOKLYN, NY

NY Spills S103037119
N/A

Site 2 of 2 in cluster K

Relative:
Higher

Actual:
1 ft.

SPILLS:

Name: ALMAX GARAGE
Address: 2712 STILLWELL AVE
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 9714501 / 2004-03-22
Facility ID: 9714501
Facility Type: ER
DER Facility ID: 108550
Site ID: 125503
DEC Region: 2
Spill Cause: Deliberate
Spill Class: C3
SWIS: 2401
Spill Date: 1998-03-30
Investigator: RWAUSTIN

Referred To: Not reported
Reported to Dept: 1998-03-30
CID: 252
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Federal Government
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 1998-03-30
Spill Record Last Update: 2004-03-22
Spiller Name: UNK
Spiller Company: ALMAX GARAGE
Spiller Address: 2712 STILLWELL AVE
Spiller Company: 001
Contact Name: UNK
DEC Memo:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was
AUSTIN FAX TO ECS 3/22/2004 - AUSTIN - HOUSEKEEPING COMPLAINT FROM 6
YRS. AGO - CLOSED - ORIG. ASSIGNED TO SIGONA - END"

Remarks: "CALLER STATES NOTIFIER TOLD HIM THAT GARAGE IS DUMPING M,ATERIALS
INTO THE STREET."

All Materials:

Site ID: 125503
Operable Unit ID: 1057372
Operable Unit: 01
Material ID: 325460
Material Code: 0043A
Material Name: antifreeze
Case No.: Not reported
Material FA: Other
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

Site ID: 125503
Operable Unit ID: 1057372
Operable Unit: 01
Material ID: 325459
Material Code: 0015
Material Name: motor oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

Name: ALMAX GARAGE
Address: 2712 STILLWELL AVE
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 9714502 / 2003-07-28
Facility ID: 9714502

Facility Type: ER
DER Facility ID: 108550
Site ID: 330891
DEC Region: 2
Spill Cause: Deliberate
Spill Class: C4
SWIS: 2401
Spill Date: 1998-03-30
Investigator: RWAUSTIN
Referred To: Not reported
Reported to Dept: 1998-03-30
CID: 211
Water Affected: Not reported
Spill Source: Gasoline Station or other PBS Facility
Spill Notifier: Local Agency
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 1998-03-30
Spill Record Last Update: 2003-07-28
Spiller Name: TERRY DEP
Spiller Company: ALMAX GARAGE
Spiller Address: 2712 STILLWELL AVE
Spiller Company: 001
Contact Name: TERRY
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was

Remarks: AUSTIN 7/28/03 - AUSTIN - SEE SPILL # 9740501 - CLOSED THIS SPILL
REPORT AND LEFT OTHER ONE OPEN - SPILL ORIG. ASSIGNED TO SIGONA, LIKE
#9704501 - END"
"CALLER REPORTS EMPLOYEES DELIBERATELY DUMPED PRODUCT IN STREET AND
PRODUCT MAY HAVE ENTERED STORM DRAIN - NO CLEAN UP"

All Materials:

Site ID: 330891
Operable Unit ID: 1057374
Operable Unit: 01
Material ID: 325461
Material Code: 0022

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

Material Name: waste oil/used oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

Site ID: 330891
Operable Unit ID: 1057374
Operable Unit: 01
Material ID: 325462
Material Code: 0043A
Material Name: antifreeze
Case No.: Not reported
Material FA: Other
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported